

COVID Considerations:

- This outage will effect the exhaust portion of the mechanical system for ground floor restrooms and the innovation lab only.
- This outage has been scheduled for a Saturday morning when the building will have minimal users.
- The ERV takes the exhausted air and runs it through a heat exchanger with the new outside air to precondition the new outside air for the AHU. With this system turned off for the outage the outside air will not be preconditioned so the AHU will run less efficiently during this time, however with the building in weekend mode the AHU is not set to full capacity so there will be minimal effects to the building temperature and COVID HVAC protocols.
- All workers will be accessing the building into the Mechanical room only so they will not be in any areas where student or faculty would be present. All workers will follow on site COVID protocols while working on campus.