


ROOM CATEGORY		
	AREA	QTY
100-CLASSROOM FACILITIES	2,673	3
200-LABORATORY FACILITIES	565	1
200-Laboratory Facilities	6,456	16
300-Office Facilities	3,571	18
700-Support Facilities	1,873	4
Non-Assignable Areas	13,784	35
TOTAL: 26,922		



ROOM	ROOM CATEGORY
028	NON-Nonassignable Areas
029	NON-Nonassignable Areas
101	NON-Nonassignable Areas
102	300-Office Facilities
105	NON-Nonassignable Areas
106	200-Laboratory Facilities
106A	200-Laboratory Facilities
106B	200-Laboratory Facilities
106D	200-Laboratory Facilities
106F	200-Laboratory Facilities
107	200-LABORATORY FACILITIES
108A	300-Office Facilities
108C	700-Support Facilities
108D	700-Support Facilities
109A	200-Laboratory Facilities
110	200-Laboratory Facilities
111	200-Laboratory Facilities
111A	NON-Nonassignable Areas
111B	200-Laboratory Facilities
111D	200-Laboratory Facilities
120	300-Office Facilities
124	NON-Nonassignable Areas
126	300-Office Facilities
127	300-Office Facilities
128	300-Office Facilities
129	300-Office Facilities
130	300-Office Facilities
131	300-Office Facilities
132	300-Office Facilities
133	300-Office Facilities
134	300-Office Facilities
135	300-Office Facilities
136	300-Office Facilities
140	200-Laboratory Facilities
154B	NON-Nonassignable Areas
C101	NON-Nonassignable Areas
C102	NON-Nonassignable Areas
C104	NON-Nonassignable Areas
C106	NON-Nonassignable Areas
C109	NON-Nonassignable Areas
C111	NON-Nonassignable Areas
C112	NON-Nonassignable Areas
C113	NON-Nonassignable Areas
V101	NON-Nonassignable Areas
V103	NON-Nonassignable Areas
V104	NON-Nonassignable Areas
V105	NON-Nonassignable Areas
V106	NON-Nonassignable Areas
V107	NON-Nonassignable Areas
V108	NON-Nonassignable Areas
X101	NON-Nonassignable Areas
X103	NON-Nonassignable Areas



Office of the
University Architect
Facilities Management
1161 West Samford Ave., Building 1
Auburn, AL 36849

ROOM CATEGORY
Davis Hall
Level: 01

Building No.: AA_X0204
File Name: AA_X0204_01
Last Export: 10/14/2019
Report Created By: Ellen Doyle
Report Date: 04/29/2020